



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 09/04/2013


Reviewed 

Mine Name: Pine Ridge	Permit Number: S/037/0120	Mine Status: Reclaimed
Operator Name: Energy Fuels Resources	Inspection Date: 08/27/2013	Permit Fees: Paid
Inspector(s): MBradley	Inspection Time: 12 noon	Bond Amount: \$7,900
Attendee(s): Tyler Johnson, EFR; Jerry Mansfield, SITLA	Weather: Cloudy	Bond Escalation: 08/31/2014
Inspection Purpose: Operator requested bond release		Prior Inspection: 10/20/2010

Conclusions and Recommendations

Overall, the site looks in good shape, except for small area recently disturbed to finish portal closure/trench backfill. Recommend release of all but \$1200 to cover revegetation and mulching of small disturbed area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Inspect recent portal closure		
3. Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
USFS had EFR install rock road blocks to prevent public access		
6. Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Closure complete, needs minor revegetation		
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Open trench/portal backfilled and closed		
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Roughened to accept seed		
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Most of pad is well vegetated. Only recent disturbed area needs seeding/mulch		
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

PBB:mpb

CC: Joel Nowak, USFS (joelnwak@fs.fed.us)
Dick White, Energy Fuels Resources (dwhite@energyfuels.com)

File: /NRLOGMFS1/OGM/GROUPS/MINERALS/WP/M037-SanJuan/S0370120-PineRidge/inspections/Inspection09042013.pdf



Closed portal area



Center of pad looking east



Center of pad looking northeast



Center of pad looking north